\$**·* * *	្រូវគឺ មាន។ ២៥២មេតុ ប្រធ			
	Approved For Release	2002/06/25 : CIA-RDP89B0	00569R000	i-0
0.43	1623Z 12 APR 64	SECRET		and the state of t
				Fig. 1 By Carlot
			St. 7	Company of the second of the s
	to go the second second second second	A COUNTY TO A COUNTY TO A COUNTY		11
÷()	DIRECTOR		The second second	The former is consistent and provide that the financial and the fi
	180	* 1	Andrew Comments	e engage of the specific of the second of th
5X1A			al earc	RITY
A TUBE			FALO	11.7.1.3
	0PS 1-8	÷	A TANK TO WE SERVED	Service 1 To the State of the Control of the Contro
		· .	4	IN 72936
	TOR: 1747Z 12 A	PR 64		
		·		
	And the second s	and the second s	مستعمل معرفي المنافي ا	Ø537
* XX	<i>3</i>			CHE
25X1A				25X1A
İ				
2		1		
1	1. ON MSN S18	4A BW SENSOR FOR RPM	FAILED AND POS	SS SENSOR FOR
V1 A	A O OF NE A MI ADMITCH	ED WE HAVE NO SPARE	SENSORS FOR THE	
X1A			À	
	2. PLS ADVISE CURRENT STATUS OF SPARE SENSORS AND SUGGEST AVAIL			
5X1A	The state of the s			
	SPARES ACCOMPANY	<i>r</i> e	iga a w waa maka a a mwa	க நாளாள் இது கொள்ளாக ப் பிக்க நக்க கொள்ளாக இவிக்கியார்.
· · · · · · · · · · · · · · · · · · ·	SP 69178 (GFE PAR	т).	* 4	

END OF MESSAGE